

# CALENDRIER DES FORMATIONS

# 2020



Max Perlès  
revêtements techniques industriels

Janvier		Février		Mars		Avril		Mai		Juin		Juillet		Août		Septembre		Octobre		Novembre		Décembre	
1 M		1 S		1 D		1 M		1 V		1 L		1 M		1 S		1 M		1 J		1 D		1 M	
2 J		2 D		2 L		2 J		2 S		2 M		2 J		2 D		2 M		2 V	<b>AIR.</b>	2 L		2 M	
3 V		3 L		3 M		3 V	<b>AIR.</b>	3 D		3 M		3 V		3 L		3 J		3 S		3 M		3 J	
4 S		4 M		4 M		4 S		4 L		4 J		4 S		4 M		4 V	<b>T.P.S.</b>	4 D		4 M		4 V	
5 D		5 M		5 J		5 D		5 M		5 V	<b>AIR.</b>	5 D		5 M		5 S		5 L		5 J		5 S	
6 L		6 J		6 V	<b>T.P.S.</b>	6 L		6 M		6 S		6 L		6 J		6 D		6 M		6 V		6 D	
7 M		7 V	<b>LAB.</b>	7 S		7 M		7 J		7 D		7 M		7 V		7 L		7 M		7 S		7 L	
8 M		8 S	<b>LAB.</b>	8 D		8 M		8 V		8 L		8 M		8 S		8 M		8 J		8 D		8 M	
9 J		9 D		9 L		9 J		9 S		9 M		9 J		9 D		9 M		9 V		9 L		9 M	
10 V		10 L		10 M		10 V	<b>LAB.</b>	10 D		10 M		10 V		10 L		10 J		10 S		10 M		10 J	
11 S		11 M		11 M		11 S	<b>LAB.</b>	11 L		11 J		11 S		11 M		11 V	<b>LAB.</b>	11 D		11 M		11 V	<b>C.M.O.</b>
12 D		12 M		12 J		12 D		12 M		12 V		12 D		12 M		12 S	<b>LAB.</b>	12 L		12 J		12 S	
13 L		13 J		13 V		13 L		13 M		13 S		13 L		13 J		13 D		13 M		13 V	<b>G.C.T.D.</b>	13 D	
14 M		14 V		14 S		14 M		14 J		14 D		14 M		14 V		14 L		14 M		14 S		14 L	
15 M		15 S		15 D		15 M		15 V	<b>T.P.S.</b>	15 L		15 M		15 S		15 M		15 J		15 D		15 M	
16 J		16 D		16 L		16 J		16 S		16 M		16 J		16 D		16 M		16 V	<b>C.M.O.</b>	16 L		16 M	
17 V		17 L		17 M		17 V	<b>C.M.O.</b>	17 D		17 M		17 V		17 L		17 J		17 S		17 M		17 J	
18 S		18 M		18 M		18 S		18 L		18 J		18 S		18 M		18 V	<b>G.C.T.D.</b>	18 D		18 M		18 V	
19 D		19 M		19 J		19 D		19 M		19 V	<b>C.M.O.</b>	19 D		19 M		19 S		19 L		19 J		19 S	
20 L		20 J		20 V	<b>G.C.T.D.</b>	20 L		20 M		20 S		20 L		20 J		20 D		20 M		20 V	<b>LAB.</b>	20 D	
21 M		21 V	<b>C.M.O.</b>	21 S		21 M		21 J		21 D		21 M		21 V		21 L		21 M		21 S	<b>LAB.</b>	21 L	
22 M		22 S		22 D		22 M		22 V		22 L		22 M		22 S		22 M		22 J		22 D		22 M	
23 J		23 D		23 L		23 J		23 S		23 M		23 J		23 D		23 M		23 V		23 L		23 M	
24 V		24 L		24 M		24 V		24 D		24 M		24 V		24 L		24 J		24 S		24 M		24 J	
25 S		25 M		25 M		25 S		25 L		25 J		25 S		25 M		25 V		25 D		25 M		25 V	
26 D		26 M		26 J		26 D		26 M		26 V	<b>LAB.</b>	26 D		26 M		26 S		26 L		26 J		26 S	
27 L		27 J		27 V		27 L		27 M		27 S	<b>LAB.</b>	27 L		27 J		27 D		27 M		27 V	<b>AIR.</b>	27 D	
28 M		28 V		28 S		28 M		28 J		28 D		28 M		28 V		28 L		28 M		28 S		28 L	
29 M		29 S		29 D		29 M		29 V	<b>G.C.T.D.</b>	29 L		29 M		29 S		29 M		29 J		29 D		29 M	
30 J				30 L		30 J		30 S		30 M		30 J		30 D		30 M		30 V	<b>T.P.S.</b>	30 L		30 M	
31 V				31 M				31 D				31 V		31 L				31 S				31 J	

**LAB.** Labellisation: mise en oeuvre des stratifiés MaxPerles

**C.M.O.** Contrôles de Mise en Oeuvre

**T.P.S.** Traitement des Points Singuliers

**G.C.T.D.** Gestion des Consommations et Traitement des Déchets

**AIR.** Matériels AIRLESS